	Туре	L #	Hits	Search Text
1	BRS	L1	3	( pierc\$3 adj2 ( roll or flare )) near3 rivet\$3
2	BRS	L2	0	( selfpierc\$3 adj2 ( roll or flare )) near3 rivet\$3
3	BRS	L3	0	( self-pierc\$3 adj2 ( roll or flare )) near3 rivet\$3
4	BRS	L4	15	(( self-pierc\$3 adj2 rivet\$3) or ( selfpierc\$3 adj2 rivet\$3)) and ( \$computer or \$processor or cpu )
5	BRS	L5	185	rivet\$3 with ( program\$4 or software )
6	BRS	L6	49	instruct\$4 near7 rivet\$3

....

	DBs	Time Stamp	Comments	Error Definitio	Errors
1	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/06 08:09			0
2		2004/09/06 08:10			0
3	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/06 08:11			0
4	JPO; DERWENT; IBM_TDB	2004/09/06 08:12			0
5	JPO; DERWENT; IBM_TDB	2004/09/06 08:12			0
6	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/06 08:14			0

	Туре	L #	Hits	Search Text
7	BRS	Ь7	185	rivet\$3 with ( program\$4 or software )
8	BRS	L8	16	(( self adj pierc\$3 adj2 rivet\$3) or ( selfpierc\$3 adj2 rivet\$3)) and ( \$computer or \$processor or cpu )
9	BRS	L9	15	(( self-punch\$3 adj2 rivet\$3) or ( selfpunch\$3 adj2 rivet\$3) or ( self adj punching adj rivet\$3 ))
10	BRS	L10	15	(rivet near7 protrud\$) with ( sense\$1 or sensing or detect\$4 or measur\$3 or measurement )
11	BRS	L11	7	(rivet near7 flush) with ( sense\$1 or sensing or detect\$4 or measur\$3 or measurement )

.

	DBs	Time Stamp	Comments	ErrorDefinitio	Errors
7	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/06 08:16			0
8	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/06			0
9	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/06			0
10	JPO; DERWENT; IBM_TDB	2004/09/06 08:21			0
11	1	2004/09/06 08:22	***************************************		0